


MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2025		Claim number				Code / Agency				Date accident 16/09/2025							
				Expert code		Adjuster code				Policy number				Injured person can recover the VAT							
Date assignment 16/09/2025		Date first survey 29/09/2025		Place Pozzuoli		C/O		Repairs		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) ALFA ROMEO JUNIOR								Plate GW475WB		Vin Chassis ZAA5AVAT0RJA01709				First Registration							
Usage status NON CONOSCIUTO		Km 36884		Tyres % 60		Color rosso		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0		Wheelbase								Seats No. 0		Axles 0			
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations										SR		LA		VE		ME		D.M. S.C.		Costs of spare parts	
										Dif Time		Dif Time		Dif Time		Time				* (VAT excluded)	
1		Aggregate size of 2 elements								S				S				S			
1 50572607		Front mudguard								L		S				S					
1 52205303		Front door								L		S				S					
1 50572738		Front bonnet								L		L				L					
1 156182150		Front bumper								L		L				L					
1 52205302		Front door								R		L		L				L			
1 156182160		Rear central bumper								S		S				S					
1 50572790		Rear hatch								L		L				L					
1 735785679		Door sill trim								L		S		S				S			
1 735784963		Front wheel arch trim								L		S		S				S			
1 735773480		External rear-view mirror cap								L		L		L				L			
1 Codice Ricambio		Ripristino disco ant sx; post dx e sx da 18																			
1 Codice Ricambio		Seconda chiave																			
1 Codice Ricambio		Carta di circolazione																			

New for old value (N)	Remarks spie attive; recarsi in officina. veicolo sporco Pneum. est. Goodyear 215/55 R18 5mm
-----------------------	--