

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2025		Claim number				Code / Agency				Date accident 23/09/2025							
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT									
Date assignment 23/09/2025		Date first survey 29/09/2025		Place CATANIA		C/O AGE		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate									
Lessee / Co-owner												Date of overhaul									
Vehicle (Brand - Model - Version) RENAULT CLIO 1.5 DCI BLUE 74KW BUSINESS berlina 2v 100CV 5P								Plate GL367HX		Vin Chassis VF1RJA00769039665				First Registration 13/09/2022							
Usage status NON CONOSCIUTO		Km 116197		Tyres % 70		Color		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts * (VAT excluded)			
								Dif		Time		Dif		Time		Dif		Time			
1	403155422R	Front wheel cap						R	S		S		S								
1	403156554R	Rear wheel cap						R	S		S		S								
1	620228966R	Front bumper							S		S		S								
1	260107933R	Headlight						R	S		S		S								
1	Codice Ricambio	Ruota di scorta compl.							S		S		S								
1	Codice Ricambio	Kit dotazione attrezzi							S		S		S								
1	Codice Ricambio	Igienizzazione tessuto							S		S		S								
1	801005036R	Front door						R	M		L		M								
1	821005029R	Rear door						R	M		L		M								
1	760309260R	rear mudguard						R	L				M								
1	901009697R	Rear hatch							M		L		M								
1	731127073R	Roof							M		M		M								
1	850226333R	Rear bumper							M		M		M								
1	963738293R	External rear-view mirror cap						L	L		L		L								
1	963749543R	External rear-view mirror cap						R	L		L		L								
1	Codice Ricambio	Parafango ant. PRM						R													

New for old value (N)	Remarks Pnreumatici ant. e post. invernali Hankook - Res. 7 mm. Veicolo sporco spia motore attiva, manutenzione da eseguire
-----------------------	---