

|                                                                                                                |  |                                               |  |                          |  |                                               |  |                                            |               |                                         |  |                                               |                                                              |                                                  |  |           |  |                                          |  |                   |  |
|----------------------------------------------------------------------------------------------------------------|--|-----------------------------------------------|--|--------------------------|--|-----------------------------------------------|--|--------------------------------------------|---------------|-----------------------------------------|--|-----------------------------------------------|--------------------------------------------------------------|--------------------------------------------------|--|-----------|--|------------------------------------------|--|-------------------|--|
| <b>MACADAM ITALY S.R.L.</b><br><br>Piazza Belgioioso, 2 - 20121 Milano (MI)<br>Tel. - Fax<br>Piva: 12729790969 |  |                                               |  | Report No.               |  | Expert's report for<br><b>Alphabet Italia</b> |  |                                            |               | Type of insurance<br><b>Perizia</b>     |  |                                               |                                                              |                                                  |  |           |  |                                          |  |                   |  |
|                                                                                                                |  |                                               |  | Policyholder             |  |                                               |  | Opposite party                             |               |                                         |  | Opposite party company                        |                                                              |                                                  |  |           |  |                                          |  |                   |  |
|                                                                                                                |  |                                               |  | Operation<br><b>2025</b> |  | Claim number                                  |  |                                            | Code / Agency |                                         |  |                                               | Date accident<br><b>06/08/2025</b>                           |                                                  |  |           |  |                                          |  |                   |  |
|                                                                                                                |  |                                               |  | Expert code              |  | Adjuster code                                 |  |                                            | Policy number |                                         |  |                                               | Injured person can recover the VAT<br><b>NOT ESTABLISHED</b> |                                                  |  |           |  |                                          |  |                   |  |
| Date assignment<br><b>06/08/2025</b>                                                                           |  | Date first survey<br><b>25/08/2025</b>        |  | Place<br><b>ZANICA</b>   |  | C/O<br><b>RIP</b>                             |  | Repairs<br><b>TO START</b>                 |               | Photo                                   |  | Lien in favor of                              |                                                              | Expiry date                                      |  |           |  |                                          |  |                   |  |
| Ownership certificate<br><b>Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)</b>                     |  |                                               |  |                          |  |                                               |  |                                            |               |                                         |  | Formerly plate                                |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| Lessee / Co-owner                                                                                              |  |                                               |  |                          |  |                                               |  |                                            |               |                                         |  | Date of overhaul                              |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| Vehicle (Brand - Model - Version)<br><b>JEEP COMPASS 1.3 T4 PHEV 190cv</b>                                     |  |                                               |  |                          |  |                                               |  | Plate<br><b>GJ338YY</b>                    |               | Vin Chassis<br><b>ZACPJFCWXNPR95691</b> |  |                                               |                                                              | First Registration<br><b>19/04/2022</b>          |  |           |  |                                          |  |                   |  |
| Usage status<br><b>NON CONOSCIUTO</b>                                                                          |  | Km<br><b>81213</b>                            |  | Tyres %<br><b>65</b>     |  | Color<br><b>BLU</b>                           |  | Type of enamel<br><b>METALLIZED/DOUBLE</b> |               |                                         |  | Consistency of damage<br><b>TO BE CHECKED</b> |                                                              | Type of Expert's report<br><b>NOT DEFINITIVE</b> |  |           |  |                                          |  |                   |  |
| Equipment                                                                                                      |  |                                               |  |                          |  |                                               |  |                                            |               |                                         |  |                                               |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| Approval code                                                                                                  |  | For commercial vehicles                       |  | Carrying Qls<br><b>0</b> |  | Tare, Q<br><b>0</b>                           |  |                                            |               |                                         |  |                                               |                                                              |                                                  |  | Wheelbase |  | Seats No.<br><b>0</b>                    |  | Axles<br><b>0</b> |  |
| Commercial value (C)                                                                                           |  | Wrecked car value                             |  | Value by difference      |  | Ancillary expenses                            |  |                                            |               |                                         |  |                                               |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| Damaged items / restoration operations                                                                         |  |                                               |  |                          |  |                                               |  | SR                                         |               | LA                                      |  | VE                                            |                                                              | ME                                               |  | D.M. S.C. |  | Costs of spare parts<br>* (VAT excluded) |  |                   |  |
|                                                                                                                |  |                                               |  |                          |  |                                               |  | Dif Time                                   |               | Dif Time                                |  | Dif Time                                      |                                                              | Time                                             |  |           |  |                                          |  |                   |  |
| 1 Codice Ricambio                                                                                              |  | Ripristino cerchio in lega ant.               |  |                          |  | L                                             |  | S                                          |               | S                                       |  | S                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 Codice Ricambio                                                                                              |  | Ripristino cerchio in lega ant.               |  |                          |  | R                                             |  | S                                          |               | S                                       |  | S                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 Codice Ricambio                                                                                              |  | Ripristino cerchio in lega post.              |  |                          |  | R                                             |  | S                                          |               | S                                       |  | S                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 60946858                                                                                                     |  | Rear wheel arch trim                          |  |                          |  | R                                             |  | S                                          |               | S                                       |  | S                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 53241004                                                                                                     |  | Upper rear mudguard trim                      |  |                          |  | R                                             |  | S                                          |               | S                                       |  | S                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 735737866                                                                                                    |  | Front bumper lower part                       |  |                          |  |                                               |  | S                                          |               | S                                       |  | S                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 52157576                                                                                                     |  | Door compartment structure with rear mudguard |  |                          |  | L                                             |  | L                                          |               | L                                       |  | M                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 53461439                                                                                                     |  | Battery recharger flap                        |  |                          |  |                                               |  | L                                          |               | L                                       |  | L                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 52141701                                                                                                     |  | Rear door                                     |  |                          |  | L                                             |  | L                                          |               | L                                       |  | L                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 52151853                                                                                                     |  | Front mudguard                                |  |                          |  | L                                             |  | L                                          |               |                                         |  | L                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 52243917                                                                                                     |  | Front door                                    |  |                          |  | R                                             |  | L                                          |               |                                         |  | L                                             |                                                              |                                                  |  |           |  |                                          |  |                   |  |
| 1 Codice Ricambio                                                                                              |  | Riparazione con tecnica a levabolli           |  |                          |  |                                               |  |                                            |               |                                         |  |                                               |                                                              |                                                  |  |           |  |                                          |  |                   |  |

|                       |                                                                                                         |
|-----------------------|---------------------------------------------------------------------------------------------------------|
| New for old value (N) | <div>Remarks</div> <p>PNEUM. ESTIVI MICHELIN/DUNLOP 235/45 R19 (5,3MM - 5,6MM).<br/>VHL GRANDINATO.</p> |
|-----------------------|---------------------------------------------------------------------------------------------------------|